

Bruker Avance III 600 MHz

June 21, 2016	System operational; TopSpin 3.2pl5 Paravision 6.0.1 UPS died. Console and gradient cabinet now hardwired.
Jan 14, 2016	5mm BBO installed
Dec 19, 2015	DIFF 30 calibrated
July 14, 2015	HRMAS installed
June 29, 2015	Micro-5 imaging
May 13, 2015	5mm BBO Installed
April 1, 2015	New AMRIS air compressor
March 15, 2015	BCU-2 died, replaced with BCU-2 from 750
March 13, 2015	HRMAS installed
March 5, 2015	5mm Imaging probe installed Merlin 33 chiller installed
Feb 24, 2015	PV6 Installed and configured Micro-coil protocols set up
Feb 16, 2015	HRMAS back up
Feb 14, 2015	Air down/system down
Feb 10, 2015	HRMAS installed/QC 4 degrees C at 6 kHz spin speed
Feb 3, 2015	5mm Imaging probe installed
Jan 14, 2015	5mm Broadband installed
Oct 6, 2014	Imaging probe installed
Sep 5, 2014	5mm Broadband installed
Aug 8, 2014	Imaging probe installed
July 23, 2014	HRMAS probe installed

June 20, 2014

Imaging probe installed

April 11, 2014

5mm Broadband probe installed

March 18, 2014

HRMAS installed