

Bruker Avance III 500 MHz

June 1, 2016	System Operational TopSpin 3.2pl5 and pl6 installed
April 4, 2016	3.2mm probe repaired
Jan 22, 2016	3.2mm solids probe is arcing
Oct 5, 2015	License issue with hosts file repaired
July 10, 2015	3.2mm Solids probe
July 6, 2015	5mm BBO installed to test 2H
June 12, 2015	3.2mm Solids probe
May 21, 2015	5mm BBO installed to test 2H
May 13, 2015	System is operational with new air compressor
Aug 02, 2014	3.2mm Solids probe installed
July 09, 2014	5mm SMART probe installed
June 16, 2014	3.2mm Solids probe installed
May 19, 2014	5mm SMART probe Installed
April 12, 2014	TopSpin 3.2.6 is available in a parallel install
April 11, 2014	Topspin 3.2.5 installed and new firmware
March 17, 2014	3.2mm Solids probe installed