

Bruker Avance III HD 750 MHz Wide Bore

June 21, 2016	System operational TopSpin 3.2pl6 Paravision 6.0 and PV 6.0.1 installed
Sept 1, 2015	Disk drive cloned for backup
July 24, 2015	Micro 2.5 gradients install and QC
July 6, 2015	Installed 3.2mm solids probe
June 4, 2015	Micro 2.5 gradients install and QC
May 18, 2015	Installed and calibrated Diff30 gradient
May 13, 2015	Mini 0.75 gradient installed –temp bypass used
April 27, 2015	DIFF60 gradient failed
April 2, 2015	Installation and QC of new 3.2mm Solids probe
April 01, 2015	New air compressor installed
March 15, 2015	BCU-2 removed to use on 600
Feb 25, 2015	Installed new Accel 250 chiller for gradients
Feb 24, 2015	Bruker visit - Verified RF shield, quad combiner
Feb 10, 2015	Mini 0.75 Gradients installed /QC. 33mm linear coil QC
Feb 05, 2015	Micro 2.5 Gradients installed/QC. 25mm coil tested
Jan 11, 2015	Mini 0.75 Gradients Installed
July 08, 2014	Master unit shut down – fuse replaced
May 26, 2014	PV 6.0 Installed
April 11, 2014	Micro 2.5 gradients installed
March 17, 2014	Diff 60 gradients installed